G. R. S. 59] GPB—15,000—22-7-14

GENERAL AND REVENUE SECRETARIAT.

1901-02
~~191~~.
(Murrai)

File No. 200

Serial Nos.

Papers Filed.

*Month*_____

SUBJECT.

Repairs to the Gopuram of Sri Ranganathaswamy at the Nagadi Taluk.

PREVIOUS REFERENCES.	LATER REFERENCES.

1501/02



From The D, Commissioner, Batticaloa & Sabaragamuwa

To The D, Secy to the Govt of Ceylon Muzrai Dept

Dated 5th June 1902

Despatched 6th June 1902

Received

General No.

A No.

Enclosure No.

Submitted to the Dewan for information. The Estimate for repair will be awaited.

7/6/02

4772
207.6.0

5328
10.VI.02

Reports that the office of Sri Ranganathaswamy temple in the Wag ikadu Talukwas struck by lightning on the night of the 25th May 1902 & that the estimate for repairing it will be sent on receipt of further report

Dy. 1346.

Bangalore District
Dy. Commissioner's Office
Bangalore 5

From,

H. A Sparkes Esq.
Dy Commissioner
Bangalore District

To,

L Avantasami Rao Esq.
Dy Secy to the Govt of Mysore
Mujrai Dept

Sir,

I have the honor to report that the Gopuram of Sri Ranganatha Swami temple in the Magadi Taluk was struck by lightning on the night of the 25th May 1902 damaging certain parts of the Gopuram and the windows. Estimate for

for its repair will be submitted to ___

Government for orders separately as

soon as it is received from [illegible]

I have the honor to be,
Sir
Your most obedient servant,

Dy. Commissioner,
Bangalore District.

1/12